

## Vehicle Inspection Checklist

Checklist Item	Status / Remarks
Free from engine/gearbox leakages	Operational
Technical check of superstructure	Operational
Functional side windows	Operational
Condition of windshield	Large star-shaped crack in the windshield
Condition of batteries	Operational
Condition of air conditioning system	Operational
Condition of exhaust system	Operational
Dashboard warning codes	None detected
Test drive findings	Leak in the exhaust manifold, causing a whistling sound while driving
Other known defects	Operational